





x 1




x 1



x 1



x 1




M6

x

70

x 2




M6

x

50

x 2







M6

x

14

x 2




M6


x

100

x 2



x 1





M6


x

14

x 2



x 1



M4




x

25

x 3

TOOLS REQUIRED (NOT PROVIDED)

Phillips Screwdriver



M6


x

100

x 2



x 1




M6

x

14

x 2

		1 M6 x 100  x 2	
		2 M6 x 70  x 2	
A		x 1	3 M6 x 50  x 2
B		x 1	4 M6 x 14  x 4
C		x 1	5 M4 x 25  x 3
D		x 1	6  x 2
E		x 1	7  x 1
F		x 1	8  SET x 2