
ASSEMBLY INSTRUCTIONS

WF320120AAW&WF320121AAW



2 PERS 40 MIN	Tool Required Not Provided

TIPPS

1. Dieses Produkt wird für die Lieferung in 2 Pakete aufgeteilt. Sie kommen möglicherweise nicht gleichzeitig an. Bitte warte geduldig .

2. Wir danken Ihnen für den Einkauf! Wir bemühen uns, Ihnen qualitativ hochwertige Produkte zu bieten. In seltenen Fällen, dass Ihr Produkt beschädigt ist, Teile fehlt oder Sie auf Probleme bei der Montage stoßen, wenden Sie sich damit bitte an unseren Kundendienst, wir werden Ihnen die beste Lösung so schnell wie möglich bieten. Um Ihr Problem schnell zu lösen, bitte stellen Sie uns einige Bilder zur Verfügung, die das Produktproblem deutlich widerspiegeln können. Vielen Dank !

3. Setzen Sie die Schrauben in die Löcher ein und ziehen Sie die Schrauben an, aber nicht zu fest, 70 % ~ 80 % ist genug, und ziehen Sie schließlich alle Schrauben an. Wenn einige Schrauben nicht mit den Löchern ausgerichtet sind oder die Montage einiger Teile schwierig ist, stellen Sie bitte den Straffheitsgrad der Schrauben um.

4. Es wird empfohlen, dass 2 Personen das Produkt installieren.

Tips


1.This product will be split into 2 packages for delivery. They may not arrive at the same time. Please wait patiently.

2.Thank you for shopping! We strive to provide you with high quality products. In rare cases that your product is damaged, missing parts or you encounter assembly problems, please contact our customer service with it, we will offer you the best solution as soon as possible. In order to solve your problem quickly, please provide us with some pictures that can clearly reflect the product problem. Thanks very much !















3. Insert the screws in holes and tighten the screws, but not too tight, 70%~80% is ok, finally tighten all the screws. If some issues happened that some screws can not target to the hole or some parts are difficult to install, please adjust the tightness of the screws.

4. 2 people are recommended to finish

Parts list















20
19
14
6
13
15
15
5
5
3
2
16
1
18
17
4
17
18
27
22
23
9
10
24
7
21
25
8
12
9
10
22
23
7
24
8
11
21
26
22
23
24
21
26

WF320120AAW


①x1 	②x1 
③x1 	④x1 
⑥x1 	⑨x2 
⑩ x2 	⑪ x1 
⑫ x1 	⑰ x2 
⑱ x2 	㉒ x3 
㉗ x1 	⑧x2 

HARDWARE

WF320121AAW

⑤x2 	⑦x2 
㉖ x2 	⑬ x1 
⑭ x1 	⑮ x2 
⑯ x1 	⑲ x1 
⑳ x1 	㉑ x3 
㉓ x3 	㉔ x3 
㉕ x1 	


Hardware

A	x52(+2)
	
Ø6x35mm	

B	x52(+2)
	
Ø15x10mm	

C	x26(+2)
	
Ø6x30mm	

D	x40(+2)
	
Ø4x35mm	

E	x2
	
Ø6x30mm	

F	x4(+1)
	

G	x4(+1)
	
Ø3x14mm	

H	x50(+2)
	
Ø3x12mm	

I	x6(+1)
	

J	x2
	


K	x2
	
Ø4x12mm	

L	x4
	
Ø6x25mm	

CL	x5
	
L300mm	


CR	x5
	
L300mm	

DL	x5
	
L300mm	


DR	x5
	
L300mm	


1


A x4




A x4








A x6




A x4




A	x18
	
Ø6x35mm	


2



H x3



H x3




H	x6
	
Ø3x12mm	

CL	x1
	
L300mm	

CR	x1
	
L300mm	

3




H	x6
Ø3x12mm	

CL	x1
L300mm	

CR	x1
L300mm	


4





C	x6
Ø6x30mm	

D	x4
Ø4x35mm	

5








B	x4
Ø15x10mm	


C	x2
Ø6x30mm	


D	x2
Ø4x35mm	


I	x2

6











A	x12
Ø6x35mm	

7


A x4




A x4




A x4








A x4



A x4







A	x20
	
Ø6x35mm	


8

H x9



H x9






H	x18
	
Ø3x12mm	


CL	x3
	
L300mm	

CR	x3
	
L300mm	

9



B x8




C x4

B	x8
	
Ø15x10mm	

C	x4
	
Ø6x30mm	


10




D x4


D	x4
	
Ø4x35mm	

11





B x8




C x4

B	x8
	
Ø15x10mm	

C	x4
	
Ø6x30mm	


12



D x8


D	x8
	
Ø4x35mm	

13




I	x4
	


14




C	x4
	
Ø6x30mm	


15






A	x2
	
Ø6x35mm	

B	x4
Ø15x10mm	




16



B	x2
	
Ø15x10mm	


17




C	x6
Ø6x30mm	

L	x4
Ø6x25mm	


18





B	x6
	
Ø15x10mm	

19



F	x4


G x4	
Ø3x14mm	

J	x2
Ø4x18mm	

K	x2
Ø4x12mm	

20






x3


H	x12
	
Ø3.5x12mm	

DL	x3
	
L300mm	

DR	x3
	
L300mm	

21








x3

D	x12
Ø4x35mm	

22








x2

B	x12
Ø15x10mm	

23




x2

H	x8
Ø3x12mm	

DL	x2
L300mm	

DR	x2
L300mm	


24





x2

D	x8
Ø4x35mm	

25










B	x8
	
Ø15x10mm	

26








27





28









E	x2
	

D	x2
	
Ø4x35mm	