



Assembly Instruction



Accessories



A: 4 PC




B: 4 PC



C: 1 PC




D: 16 PC



E: 1 PC




F: 1 PC




G: 1 PC



Step 1



Step 2



Step 3



Step 4

